

*Thunderbird Specialists*

**CASCO**

SINCE 1969

This fuel sending unit has been calibrated for the 1956 Thunderbird. Empty is shown on the gage when needle is on the the first square not to the left of the first square. Some dash units might not register completely full. Please do not bend float arm.

