

Thunderbird Specialists

CASCO

SINCE 1969

Classic Auto Supply Co., Inc. 795 High Street Coshocton OH 43812

Enclosed are our quality duplications of the unique factory inspection stamps.

- Clean all stamp locations.
- Trim the individual decals leaving 1/8" to 1/16" border around the yellow markings.
- Peel off the backing and apply.

<u>DECAL</u>	<u>LOCATION</u>
ROAD TESTED (2).....	On each door rear edge just below the Garnish Moulding
FINAL INSPECTION.....	Right inner fender panel front between voltage regulator and generator location
PAINT INSPECTION (2)...	Bottom of Hood frame approx. 20" from rear (top) left corner and under dash near headlight switch
GLASS INSPECTION	On firewall behind battery – between hood latch and main harness
TRIM INSPECTON	Firewall right hand side near hood catch assembly
DATE.....	On heater core frame facing battery side of car (56-57 only)
6VOLT, 12 VOLT	On round motor part of heater blower assembly

Parts: 740/622-8561 Restorations: 740/622-9700 Fax: 740/622-5151

